WASHER THERMOCOUPLE

STYLE WT



- Maximum temperature from 400°F to 900°F (204°C to 482°C) based on wire type
- J, K and T calibrations available
- For #6, #8, #10 and 1/4" screw sizes
- Grounded or ungrounded junction
- Flexible

ORDERING INFORMATION

W	T	1	2	–	3	4	4	–	5	6	7	–	8	8	8	9	10

To create an ordering code fill in the boxes above with the appropriate number and/or letter from the corresponding box below.

Box 1: Calibration Code
J = J Type, ANSI Standard Tolerances
K = K Type, ANSI Standard Tolerances
T = T Type, ANSI Standard Tolerances

Box 2: Number of Junctions
1 = Single (Standard)
2 = Duplex

Box 3: Junction*
G = Grounded
U = Ungrounded
** Dual ungrounded junctions are isolated*

Box 4: Screw Size
06 = #6
08 = #8
10 = #10
14 = 1/4"

Box 5: Lead Wire Construction
A = Solid
B = Stranded

Box 6: Lead Wire Insulation
G = Fiberglass (900°F/482°C)
Q = High Temp Fiberglass (1300°F/704°C)
T = Teflon (400°F/204°C)
K = Kapton (500°F/260°C)

Box 7: Lead Wire Protection
N = None
B = SS Overbraid

Box 8: Length *fill in measurement desired*
Whole inches: 001" to 999"
(Lengths over 999" consult TTI)

Box 9: Termination
A = 3/4" Stripped Leads
B = Spade Lugs
C = Spade Lugs with BX Connector
D = Standard Male Plug (350°F/177°C)
E = Medium-Temp. Male Plug (500°F/260°C)
F = High-Temp. Male Plug (800°F/426°C)
G = Standard Female Jack (350°F/177°C)
H = Medium-Temp. Female Jack (500°F/260°C)
J = High-Temp. Female Jack (800°F/426°C)
K = Miniature Male Plug (350°F/177°C)
L = Miniature Med-Temp. Male Plug (500°F/260°C)
M = Miniature Female Jack (350°F/177°C)
N = Miniature Med-Temp. Female Jack (500°F/260°C)

Box 10: Special Limits of Error
N = None
S = Special Tolerance Wire